

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the School :

MA'DIN Knowledge Garden

1. Name of the Officer
2. Location
3. Period for which the certificate is issued
4. Types of building
5. Nature of defect if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and windows
  - d) Wood work wrought and put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (Cracks if any)
6. Any Major defects notices which will render the building unsafe in any manner
7. Whether maintenance works have been done properly
8. Whether the structure is sound or not for conducting classes

: Renji Xavier C

: South Punnayur / chavakk

: 2025-26 up to 31 March

: Size as per the sheet attached

: NIL

: Yes

: Sound for conducting clas. under normal weather conditi


- Note:-
1. The stability of the structure should be examined also with reference to locatio altitude intensity of wind exposure or flood etc.
  2. Any additional observation if deemed necessary for the certificate may be furnishe separately with the certificate.

## CERTIFICATE

Certified that the School was inspected by me on ... 31/5/2025 ...  
and found to be fit / ~~unfit~~ to conduct classes for the period ... 2025-2026 ...  
for the reason stated above.

Place: Punnayur  
Date: 31/5/2025

(Seal)



  
Assistant Engineer  
ASSISTANT ENGINEER  
LSGD SECTION  
PUNNAYOOR GRAMA PANCHAYATH

# PUNNAYOOR SCHOOL

## GROUND FLOOR


SI No	ROOMS	No	L	B	D
1	PRICIPAL ROOM	1	7.00	4.80	3.48
2	ACCOUNTS ROOM	1	4.50	4.80	3.48
3	CLASS ROOM	8	7.30	7.30	3.48
5	PRAYER ROOM	1	4.60	7.30	3.48
6	ABLUTION	1	2.50	7.30	3.48
7	MINI HALL	1	13.80	7.30	3.48
8	ELECTRIC ROOM	1	4.10	7.10	3.48
9	MANAGER ROOM	1	3.08	7.10	3.48
10	WASH ROOM 1	1	3.50	5.90	3.20
11	WASH ROOM 2	1	3.50	5.55	3.20
	<b>TOTAL</b>	<b>17</b>			

## FIRST FLOOR

SI No	ROOMS	No	L	B	D
1	COMPUTER ROOM	1	13.80	7.30	3.48
2	CLASS ROOM	9	7.30	7.30	3.48
3	STAFF ROOM	1	7.30	9.10	3.48
5	PRAYER ROOM	1	4.60	7.30	3.48
6	ABLUTION AREA	1	2.50	7.30	3.48
7	WASH ROOM 1	1	3.50	5.90	3.20
8	WASH ROOM 2	1	3.50	5.55	3.20
	<b>TOTAL</b>	<b>15</b>			


## SECOND FLOOR


SI No	ROOMS	No	L	B	D
1	LIBRARY ROOM	1	13.80	7.30	3.48
2	CLASS ROOM	<del>10</del> 9	7.30	7.30	3.48
3	STAFF ROOM	1	7.30	9.10	3.48
5	ABLUTION AREA	1	2.50	7.30	3.48



ASSISTANT ENGINEER  
 LSGD SECTION  
 PUNNAMOOR GRAMPANCHAYATU

SI No	ROOMS	No	L	B	D
6	PRAYER ROOM	1	4.60	7.30	3.48
7	WASH ROOM 1	1	3.50	5.90	3.20
8	WASH ROOM 2	1	3.50	5.55	3.20
	<b>TOTAL</b>	<del>15</del> 15			



  
 ASSISTANT ENGINEER  
 LSGD SECTION  
 PUNNAYOOR GRAMA PANCHAYATH